

ROBINSON HELICOPTER COMPANY

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

To: All R22 and R44 Service Centers

15 January 2008
Rev: 4 April 2008

R22 & R44 FIELD OVERHAUL KITS

Complete field overhaul kits combine the overhaul/exchange components together with the new parts necessary to perform the R22 or R44 airframe overhaul in the field. These packages make it easy to order all of the necessary parts at a discounted price. Dealers/Service Centers receive a 10% discount on kit prices (no discount on core charges).

Field Component Overhaul Kit:

Includes new main rotor and tail rotor blades, spindles, flex plates, fanwheel, belts, etc. Also includes complete set of overhauled/exchange components (main & tail gearboxes, swashplate, clutch, actuator, fanshaft, pitch control, TR driveshaft, and shoulder harness). Raven I & II kits include exchange hydraulics. Dealers/Service Centers may either submit exchange components to the factory in advance or pay a core charge, which is refunded upon receipt of acceptable core components. Core charge includes a US\$ 500.00 core for the tail rotor assembly. Please specify aircraft serial number when ordering.

<u>Description</u>	<u>Part Nbr</u>	<u>Kit Price (US\$)</u>	<u>Core Nbr</u>	<u>Core Price (US\$)</u>
R22 Beta	R7351	\$ 68,000	R7352	\$ 16,633
R22 Beta II	R7951	\$ 68,000	R7952	\$ 16,533
R44 Astro	R7543	\$ 110,000	R7544	\$ 22,272
R44 Raven I	R8209	\$ 106,000	R8211	\$ 42,700
R44 Raven II	R8210	\$ 112,000	R8212	\$ 42,700

Engine Build-Up Kits

Includes oil lines and all engine cooling panels. *Do not order if purchasing a Robinson Overhauled engine as build-up is included.*

<u>Description</u>	<u>Part Nbr</u>	<u>Price (US\$)</u>
O-320 Engine Build-up	R8299	\$ 2,300
O-360 Engine Build-up	R8300	\$ 2,200
O-540 Engine Build-up	R8301	\$ 2,800
IO-540 Engine Build-up	R8302	\$ 3,400

Interior Overhaul Kit:

Includes new seats, carpets, insulation, cyclic and collective boots, etc. *Must specify color* (blue, gray, brown, or tan) *and heater* location (none, aft, forward single, or forward dual).

<u>Description</u>	<u>Part Nbr</u>	<u>Price (US\$)</u>
R22 Velour Interior	R8005	\$ 2,400
R22 Leather Interior	R8013	\$ 2,600
R44 Velour Interior	R8010	\$ 4,800
R44 Leather Interior	R8014	\$ 5,400

For further information or questions please contact Customer Service: Tel: (310) 539-0508, Fax: (310) 539-5198; Email: customerservice@robinsonheli.com.